

100

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Media Print Mail

Address <http://sitedevelopment.geoneering.com/e/signup.html> Go Links

**B R Y A N T
CONSULTANTS**

124 ~ [LOG IN]
126 ~ [GEONEERING HOME PAGE]

REGISTRATION

Usage of this system is restricted to those individuals and companies approved by Bryant Consultants, Inc. If you would like an account, please fill in the form below, indicate your acceptance of the User Agreement, and click "Submit".

102

Name: (First) 104 (MI) 106 (Last) 108

Company Name: 110

Address: 114

City, State, ZIP: 116

Company Web Site: <http://> 118

Your Email: 120

Phone Number: 122

User Agreement:

Bryant Consultants, Inc., and Earthsystems Technologies are all in and of the same company. For the purposes of this User Agreement and Privacy Statement, Bryant Consultants, Inc. will represent by both entities.

Scope
This Terms of Use of Earthsystems Technologies, Inc. Content ("Agreement") is applicable to any content that is provided by Earthsystems Technologies, Inc. that you access by virtue of the Web site from which you are accessing this

2/31

200

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Media Favorites Links

Address <http://sitedevelopment.geoneering.com/e/login.html?stateInfo=eLHcEjtacBbdajYq8833|3> Go

B R Y A N T
CONSULTANTS

208 ~ [LOG IN]
210 ~ [GEONEERING HOME PAGE]

Login

User ID 202

Password 204

Log In 206

[LOG IN] [GEONEERING HOME PAGE]

FIG. 2

3/31





FIG. 3

FIG. 4



5/31

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back View Favorites Search Media

Address http://sitedevelopment.geoneering.com/e/mt_projects.html?mode=edit&projectID=56&stateInfo=eLHcEjacBbdaYq8833|7 Go Links

BRYANT CONSULTANTS

306 ~ [PROJECT ADMIN] 310 ~ [CONTACT ADMIN]
308 ~ [GEONEERING] 312 ~ [GEONEERING OVERVIEW] 314 ~ [LOG OUT]

EDIT PROJECT

Project Name: Providence Phase I

Start Date: 11/12/02 504 502

End Date: ? 506 508

Save project 510

Back to Project Admin 512

Work with this project 514

Audit Info
Created: 11/12/02 11:38:30 17 - demo
Updated: -

FIG. 5

6/31

FIG. 6

600

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media

Address <http://sitedevelopment.geoneering.com/e/contactadmin.htm?stateInfo=eLHcEjtaCBBdaJYq883318> Go Links

BRYANT CONSULTANTS

306 ~ [PROJECT ADMIN] 312 ~ [ENGINEERING OVERVIEW]
608 308 ~ [ENGINEERING] 614 314 ~ [LOG OUT]

General Contacts Project Contacts

This is your general list of contacts. Each of these people may serve in one or more roles in any of your projects.
Select one of your contacts to edit, or click "New" to add a new contact.

Name	Company	Email	Phone	
Bond, James	Britts Intell	jbond@007.com	555-555-5555	NEW 616
Smith, John	Smith Company	jsmith@smithco.com	555-555-5555	
Richards, Ben	Richards Engineers	brichards@richards.com	555-555-5555	
Hoffa, Jimmy	Site Concrete		555-555-5555	
Jones, Basketball	Hoop it up	bjones@hoop.net	555-555-5555	
Fraser, Dave	US Homes	dfraser@ushomes.com	555-555-5555	
Thirwell, Kevin	City of Dallas		555-555-5555	
Quest, John	Quest Engineering	jquest@quest.com	555-555-5555	
Jack, Ripper	Cutting Edge Technologies	jripper@oj.com	555-555-5555	
Tracy, Dick	Tracy Investigations	dtracy@thetracy.com	555-555-5555	602 604

7/31

700

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media

Address http://sitedevelopment.geoneering.com/e/mt_clientcontacts.html?rowid=0X0000060e6&stateInfo=eLHcEjIacBbdajYq8833 9 Go Links

**BRYANT
CONSULTANTS**

306 ~ [PROJECT ADMIN] 310 ~ [CONTACT ADMIN]
308 ~ [GEONEERING] 312 ~ [GEONEERING OVERVIEW]
314 ~ [LOG OUT]

Contact Administration

Last Name: Smith 704
First Name: John 702
Company: Smith Company 706
Email: jsmith@smithco.com 708
Phone: 555-555-5555 710

712 Submit 714 Delete 716 Back to List of Contacts

Audit Info
Created: 10/31/02 11:10:37 15 -
Updated: -

FIG. 7

8/31

800

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Go Links

Address <http://sitedevelopment.geoneering.com/e/project.html>

**B R Y A N T
CONSULTANTS**

Contact Administration 306 ~ [PROJECT ADMIN] 312 ~ [GEONEERING OVERVIEW]
Project: Swampland Estates Phase I [!] 308 ~ [GEONEERING] 314 ~ [LOG OUT]

General Contacts Project Contacts

This is a list of contacts that apply to the project: "Swampland Estates Phase I"
You should select a contact for each role. If you need to define a new contact to show up in one of the pull-down lists, click the "General Contacts" tab. 804

Environmental:	<input checked="" type="radio"/> Bond, James - Brits Intell	802 ~ <input type="radio"/> Unknown for now
Civil:	<input checked="" type="radio"/> Hoffa, Jimmy - Site Concrete	<input type="radio"/> Unknown for now
Geotechnical:	<input checked="" type="radio"/> Quest, John - Quest Engineering	<input type="radio"/> Unknown for now
Structural:	<input checked="" type="radio"/> Ripper, Jack - Cutting Edge Technologies	<input type="radio"/> Unknown for now
Land Developer:	<input checked="" type="radio"/> Tracy, Dick - Tracy Investigations	<input type="radio"/> Unknown for now
Site Development:	<input checked="" type="radio"/> Smith, John - Smith Company	<input type="radio"/> Unknown for now

814 ~ [Save Contact Information]

FIG. 8

9/31

FIG. 9

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Media

Address <http://sitedevelopment.geoneering.com/e/geoneering.html?stateInfo=eLHcEJtacBbdajYq8833> 13 Go Links

BRYANT CONSULTANTS

Geoneering
Project: Swampland Estates Phase I [!]

306 ~ [PROJECT ADMIN] 310 ~ [CONTACT ADMIN] 312 ~ [GEONEERING OVERVIEW] 314 ~ [LOG OUT]

910 912 914 916 918 920

Risks Civil Site Development Environmental Geotechnical Structural

Civil

324 ✓ Setup up a meeting with all interested parties on civil engineering site challenges. (Done) ☐ Done ~ 328

326 ⚠ Contact civil engineer for an erosion control recommendation. ☐ Done ~ 328

326 ⚠ Review detail design of structural engineer. ☐ Done ~ 328

326 ⚠ Contact Earth Systems Technologies on a plan of action on surface and subsurface water migration. ☐ Done ~ 328

326 ⚠ ☐ Send Email ~ 322 ☐ Send Email ~ 322

326 ⚠ Contact civil engineer to validate the final grades and drainage. ☐ Done ~ 328

326 ⚠ ☐ Send Email ~ 322 ☐ Send Email ~ 322

326 ⚠ Site Development (Incomplete) ~ 330

326 ⚠ Some questions have not been answered. Click the "Site Development" tab and make sure to answer all of the questions.

10/31

FIG. 10

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print

Address <http://sitedevelopment.geoneering.com/e/geoneering.html?tab=Civil&stateInfo=eLHcEjacBbdajYq8833> | 14 Go Links

1000

BRYANT
CONSULTANTS

Geoneering
Project: Swampland Estates Phase I [!]

306 ~ [PROJECT ADMIN] 310 ~ [CONTACT ADMIN]
312 ~ [GEONEERING OVERVIEW] 314 ~ [LOG OUT]

Risks Civil Site Development Environmental Geotechnical Structural

Have you participated in an early development, pre-construction meeting to evaluate potential civil site challenges? More Info ~ 1004

1006 ~ Yes 1008 ~ No
1010 ~ Don't know 1012 ~ Skip for now

Has the civil engineer provided positive grades on each of the building lots? More Info ~ 1004

1006 ~ Yes 1008 ~ No
1010 ~ Don't know 1012 ~ Skip for now

Has a sufficient pad design been done to avoid excessive cut and fill beneath the building pads? More Info ~ 1004

1006 ~ Yes 1008 ~ No
1010 ~ Don't know 1012 ~ Skip for now

11/31

1500




FIG. 11

12/31




FIG. 12

13/31




FIG. 13

14/31

1900

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print

Address http://sitedevelopment.geoneering.com/e/mt_settings.html?rowid=0x00005d80&stateinfo-eLHcEjtacBbdajYq88833|25 Go Links

BRYANT CONSULTANTS

MAINTAIN SYSTEM SETTINGS

1908 [ADMIN MAIN MENU]
1910 [LOG OUT]

1912 Account ID: *

1914 ID Type: All

1916 Setting Type: General

1918 Setting Name: Session Timeout Period

1920 Setting Value: 3600

1922 Setting Description: Number of seconds to keep a web user's session active while waiting for a response from them. If the user simply goes away without hitting the site for too long, their session will be

1902 Submit 1904 Delete

1906 Back to List of Settings 1928

Audit Info
Created: 8/17/00 15:12:45 Web User - ?
Updated: 11/04/02 12:54:34 2 -

1908 [ADMIN MAIN MENU] [LOG OUT] 1910

FIG. 14

15/31




FIG. 15

16/31




FIG. 16

17/31




FIG. 17

18/31

2300

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Media

Address http://sitedevelopment.geoneering.com/e/mt_siteusers.html?rowid=0X0000ec82&stateInfo=eLHcEjIacBbdajYq8833 [32] Go Links

**B R Y A N T
CONSULTANTS**

Maintain System Users

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

2332

17 (Automatically assigned)
demo (Login ID)
qhbaenldxDkMyYcj (Encoded - not actual password)
? (MM/DD/YY)
? (MM/DD/YY)

☐ (Check this box to make the user an admin user!)

8- Demo ☒ [Maintain Client List]

0 (Reset to zero if user is locked out!)

0

2314 ~ User ID:
2316 ~ User Name:
2318 ~ Password:
2320 ~ Start Date:
2322 ~ End Date:
2324 ~ Admin User:
2326 ~ Client:
2328 ~ Failure Count:
2330 ~ Phone:

2302 ~ Submit Delete 2304
2306 ~ Back to List of Users 2312

Audit Info
Created: 11/12/02 11:05:02 5 - kzjones
Updated: 11/12/02 10:59:32 14 - mgehrig

2308 ~ [ADMIN MAIN MENU] [LOG OUT] ~ 2310

FIG. 18

19/31

FIG. 19

2400

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media

Address http://sitedevelopment.geoneering.com/e/brws_questions.html?stateInfo=eLHcEJtacBbdaYq8833 35 Go Links

2406

NEW

314

1802 [ADMIN MAIN MENU] [LOG OUT]

Maintain Questions 2408

2410

FIND

Showing items 1 - 10 of 32

ID	Area	Sort	Text	ActionURL
1 37	C	0	Have you participated in an early development, pre-construction meeting to evaluate potential civil site challenges?	1004 ~ More Info
2 19	C	2	Has the civil engineer provided positive grades on each of the building lots?	1004 ~ More Info
3 20	C	4	Has sufficient pad design been done to avoid excessive cut and fill beneath the building pads?	1004 ~ More Info
4 21	C	6	Has the erosion control been addressed in the civil engineering report?	
5 22	C	8	Has retaining structures been identified for this site?	
6 23	C	10	Has civil engineer provided control of surface and subsurface water migration, if the potential exists?	1004 ~ More Info
7 24	C	12	Have the final grades and drainage been validated as specified in the civil engineering design document?	1004 ~ More Info
8 29	D	0	Does the tree canopy extend over the building site pad?	

2416 2418 2420

2422

2424 2402 2404

20/31

FIG. 20

2500

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Media Favorites Links

Address http://sitedevelopment.geoneering.com/e/mt_questions.html?rowid=0X0000e0a0&stateInfo=eLHcEjtaC8BdaYq8833 36

BRYANT CONSULTANTS

Maintain Questions

1802 ~ [ADMIN MAIN MENU] 314 ~ [LOG OUT]

37 (Automatically assigned)

Civil ☒ (Within the area selected)

0 (Within the area selected)

Have you participated in an early development, pre-construction meeting to evaluate potential civil site challenges?

 More Info

2524 2526 2528 2530

Yes: ☐ No: ☒ Skip: ☐ DK: ☐ 103 [View Risk List...]

procs/mailto, p (User relative path)

2502 ~ Submit ~ 2504


2506 ~ Back to List of Questions ~ 2512

Audit Info

Created: 11/12/02 09:14:25 2 -

Updated: 11/12/02 09:15:40 2 -

2508 ~ [ADMIN MAIN MENU] [LOG OUT] ~ 2510



22/31

FIG. 22

2700

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Search Media Favorites

Address http://sitedevelopment.geoneering.com/e/mt_risks.html?rowid=0x00005fe47stateInfo=eLHcEjIacBbdajYq8833 Go Links

BRYANT
CONSULTANTS

Maintain Risks

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

102 (Automatically assigned)

2714 ~ Risk ID: Civil

2716 ~ Risk Area: 0 (Within the area selected)

2718 ~ Sort ID: Setup up a meeting with all interested parties on civil engineering site challenges

2720 ~ Risk Text:

2722 ~ Action URL:

2724 ~ Distributing List: E,C,G,S,D enter role codes E,C,G,S,D

Audit Info

Created: 10/30/02 07:39:18 2 -

Updated: 10/31 Audit fields are automatically maintained


2706 ~ Submit Delete 2708

2710 ~ Back to List of Risks 2712

[ADMIN MAIN MENU] [LOG OUT]

23/31

FIG. 23



2900

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Home Search Favorites Media Print Mail

Address http://sitedevelopment.geoneering.com/e/mt_contacts.html?rowid=0x00060e6&stateInfo=eLHcEjtacBbdajYq8833 42 Go Links

**B R Y A N T
CONSULTANTS**

Maintain System Contacts

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

16 (Automatically Assigned)

☒ [Maintain Client List]

2912 ~ Contact ID: 2914 ~ Client: 8 - Demo

2916 ~ Last Name: Smith

2918 ~ First Name: John

2920 ~ Company: Smith Consultants

2922 ~ Email: john@geoneering.com

2924 ~ Phone: 555-555-5555

2906 ~ Submit Delete ~ 2908

2910 ~ Back to List of Contacts

Audit Info

Created: 10/31/02 11:10:37 15 -

Updated: -

[ADMIN MAIN MENU] [LOG OUT]

FIG. 24

25/31

3000

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Links

Address http://sitedevelopment.geoneering.com/e/brws_eventlogs.html

Go

BRYANT
CONSULTANTS

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

System Events

Starting: 10/27/02 3002

Ending: 11/26/02 3004

3006 ~ Show Events

ID	Date	Time	Event	User ID	Client ID
253	11/11/02	9:55:58	Login Failure: User demo1	0	0
254	11/11/02	9:56:09	Login Failure: User demo1	0	0
255	11/11/02	9:56:28	Login Failure: User demo1	0	0
256	11/11/02	9:56:39	Login Failure: User kzjones	0	0
257	11/11/02	9:56:54	Login Failure: User kzj	0	0
258	11/11/02	9:57:18	Login Failure: User kzj	0	0
259	11/11/02	9:57:54	Login Failure: User kzjones	0	0
3008	3010	3011	3012	3014	3016

FIG. 25

26/31

3100

Track User Sessions and Hits - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Reload Home Search Favorites Media

Address <http://sitedevelopment.geoneering.com/e/essmenu.html?stateInfo=eLHcEjIacBbdajYq8822|47> Go Links

BRYANT
CONSULTANTS

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

Session and Hit Tracking

3102 ~ Choose A Report ☒

From Date: 11/26/2002 3104 End Date: 11/26/2002 3106

From Time: 00:00:00 3108 End Time: 10:57:23 3110

3112 ~ Submit Request

Notes:
*When listing Sessions, do not request more than about a day at a time.
**When listing Hits, do not request more than an hour or two.

[ADMIN MAIN MENU] [LOG OUT]

FIG. 26

27/31

3200





FIG. 27

28/31

Site Administration - Microsoft Internet Explorer				
File Edit View Favorites Tools Help				
Back Forward Stop Search Favorites Media Print View Source Go Links				
Address http://sitedevelopment.geoneering.com/e/sessiontrace.html?sessionid=eLHcEjtacBbdajYq8833&stateInfo=eLHcEjtacBbdajYq8833 59				
Hit #	Date & Time	Object Run	Query	Cookies
1	11/26/02 - 10:37:00	signup	GET:	valuedGuest = Yes 010
2	11/26/02 - 10:37:50	login	GET: stateInfo = eLHcEjtacBbdajYq8833 1	valuedGuest = Yes 010 safeSessionID = eLHcej
3	11/26/02 - 10:38:07	signup	GET:	valuedGuest = Yes 010 safeSessionID = eLHcej
4	11/26/02 - 10:38:57	login	GET: stateInfo = eLHcEjtacBbdajYq8833 3	valuedGuest = Yes 010 safeSessionID = eLHcej
5	11/26/02 - 10:39:29	login	POST: stateInfo = eLHcEjtacBbdajYq8833 4 adminuser = demo password = demo runAction = Log In	valuedGuest = Yes 010 safeSessionID = eLHcej

FIG. 28

3300






FIG. 29B




FIG. 30




FIG. 31